



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent Application of:

Seung-hoon KIM

Application No.: 10/602,630

ATTENTION

Confirmation No.: 8987

CERTIFICATE OF CORRECTION

Filed: June 25, 2003

BRANCH

U.S. Patent No.: 7,116,625

Batch No.:

Issued: October 3, 2006

For: APPARATUS AND METHOD FOR DETECTING POSITION OF A PICKUP

REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents
 PO Box 1450
 Alexandria, VA 22313-1450

*Certificate
FEB 18 2007
of Correction*

Sir:

Patentee(s) respectfully request(s) that a Certificate of Correction be issued in the subject patent, pursuant to 35 USC § 254 and 37 CFR § 1.322, to correct the error(s) shown on the attached Form PTO-1050. A check in the amount of \$100 to cover the cost of the Certificate is attached.

One or more of the errors shown on the attached Form PTO-1050 is or are within the responsibility of the applicant; each thereof is of a clerical or typographical nature or of minor character and occurred in good faith, and the correction thereof is consistent with the prosecution record.

Respectfully submitted,

STAAS & HALSEY LLP

Date: Feb. 5, 2007By: Gene M. Garner, II

02/06/2007 JADDO1 00000002 7116625
 01 FEB 18 2007
 Gene M. Garner, II
 Registration No. 34,172

100.00 OP

1201 New York Ave, N.W., 7th Floor
 Washington, D.C. 20005
 Telephone: (202) 434-1500
 Facsimile: (202) 434-1501

*FEB 12 2007
(FEB 12 2007)*

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO : 7, 116,625

DATED : October 3, 2006

INVENTOR(S) : Seung-hoon KIM

It is certified that error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Col. 7, line 50, change "and," to --and--

Col. 8, line 33, after "speed", delete "speeds"

MAILING ADDRESS OF SENDER:

STAAS & HALSEY
1201 New York Avenue, N.W.
7th Floor
Washington, DC 20005

PATENT NO.

No. of add'l copies
@ 304 per page

⇒

FEB 12 2007